



**Technical Service
Information Bulletin**

March 12, 2007

Title:

**TRUNK PARTITION NET STRAP TOO
SHORT FOR VERTICAL INSTALLATION**


Models:

'07 LS 460/460L

BODY
BO001-07

Introduction Some 2007 model year LS 460/460L vehicle customers may complain that the trunk partition net strap is too short for vertical installation.

The trunk partition net has been improved for this condition. Use the procedure below to correct this concern.



**Applicable
Vehicles**

- 2007 model year **LS 460/460L** vehicles produced **BEFORE** the Production Change Effective VINs shown below.

**Production
Change
Information**

MODEL	PRODUCTION CHANGE EFFECTIVE VIN
LS 460	JTHBL46F#75005949
LS 460L	JTHGL46F#75002720

**Warranty
Information**

OP CODE	DESCRIPTION	TIME	OFP	T1	T2
BD7021	Replace Trunk Partition Net	0.2	64230-50020	99	57

Applicable Warranty*:

This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



**Parts
Information**

PREVIOUS PART NUMBER	CURRENT PART NUMBER	PART NAME	QTY
64230-50020	64230-50021	Net Assembly, Room Partition	1

**Repair
Procedure**

Order and replace the trunk partition net. Follow the installation instructions in the package to install the NEW partition net.