



**Technical Service
Information Bulletin**

June 11, 2007

Title:

LOW ENGINE OIL LEVEL WARNING MESSAGE

Models:

'07 LS 460/460L

ELECTRICAL
EL009-07

Introduction On new LS 460/460L vehicles that have not had their first oil change service, customers may experience a condition where the Low Engine Oil Level warning message is illuminated even though the oil is at the correct level. Chemical residue from the assembly process may have entered the oil causing the level sensor to read inaccurately. Changing the oil and filter will correct this condition.



NOTE:
This phenomenon will more likely occur when the gear selector is in the Sport 4 (S4) mode.

- Applicable Vehicles**
- **2007** model year **LS 460/460L** vehicles produced **BEFORE** the Production Change Effective VINs shown below.

Production Change Information

MODEL	PRODUCTION CHANGE EFFECTIVE VIN
LS 460	JTHBL46F*75037351
LS 460L	JTHGL46F*75015414

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
EL7014	Engine Oil Change	0.9	90430-12031	8C	99


Applicable Warranty*:
This repair is covered until the first scheduled maintenance in accordance with the 2007 Scheduled Maintenance Guide.

* Warranty application is limited to correction of a problem based upon a customer's specific complaint.



**Repair
Procedure****NOTE:**

Be sure to use the recommended oil grade and viscosity as referred in the Owner's Manual.



Change engine oil and reset the maintenance reminder.

NOTE:

This TSIB should be done **ONLY** once. Dealers will **NOT** be reimbursed for additional claims.